





# Melt Bolt MgO Thermocouple

Style M, N, & O



### Construction

M = 3" Melt Bolt  
 N = 4" Melt Bolt  
 O = 6" Melt Bolt

### Calibration

J = Type "J"  
 K = Type "K"  
 Contact factory for other types

### Single/Duplex

0 = Single (2 wire)  
 4 = Duplex (4 wire)

### Junction Type

G = Grounded, Round Tip  
 U = Ungrounded, Round Tip

### Sheath Diameter (inch)

B = 1/8 (.125)  
 C = 3/16 (.188)

### Tip Length ("A")

Whole Inches: Example 02 = 2 inches

### Tip Length ("A" Fractional)

N = None    H = 1/8  
 B = 1/8     M = 3/4  
 D = 1/4

### Special Options

N = None  
 C = Cable Clamp on Connector  
 F = BX Connector on Leads  
 M = Supply with Mating Connector  
 S = Solid Pins on Plug

### Leadwire Terminations

B = Standard Male Plug 400° F  
 C = Standard Female Jack 400° F  
 F = Miniature Male Plug 400° F  
 G = Miniature Female Jack 400° F

### Leadwire Length ("B")

Whole Inches: Examples: 048 = 48 inches

Note: For Rigid Mount Plug, insert "000"